Dickson

Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

8" (203mm) Temperature & Humidity Chart Recorder



Specifications

Alarm Type: Audio/Visual on High/Low Limits Ambient Operating RH Conditions: 0-95% RH non-condensing Ambient Operating Temperature Conditions: 32 to 120F (0 to 50C) Approvals: CE Battery Backup: Four AA Batteries. Powers unit for up to 3 Days. Battery Life (Avg): 76 Hours (Back-up Only) Calibration Options: N100, N300, N400 Channels: CH1: Temperature, CH2: Humidity Chart Rotation Speed: 24 Hour, 7 Day or 31 Day Dew Point Accuracy: +/-3.6F from 30 to 95% RH (Calculated) (+/-2C from 30 to 95% RH (Calculated)) **Dew Point Range:** 32 to 122F (0 to 50C) **Dimensions:** 3.1 x 9.2 x 9.2in Display Dimensions Height: 1.375 **Display Dimensions Width: 2.0** Display Resolution: 0.1 Display Type: LCD **Enclosure:** Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial Humidity Accuracy: +/-2% RH from 5 to 95%; +/-2% RH from 5 to 95% Humidity Range: 0-95% RH non-condensing Humidity Sensor Type: Field Replaceable IP Rating: 20 Included Accessories: AC Adapter, Red and Blue Pen, Four AA Batteries, Quick Start Guide and Probe. *Charts sold separately.

Keypad Functions: Power On/Off, Pen Home, Alarm

Mounting Options: Free Standing or Wall Mount (With Keyhole) Power Cord: 6 ft Power Source: 120 to 240 VAC, 12 VDC (INTL fittings available); AC Adapter Power Status Indicator: LED Indicator Remote Probe Dimensions : Replaceable Sensor houses thermistor and RH sensor in polycarbonate plastic 2.5" x .8" x .5" Remote Sensor Length: 10 ft (single 10 ft extension cable available without sacrificing accuracy) Remote Sensor Type: Digital Temperature Sensor - Replaceable Response Time: 5 Minutes to 63% of Full Scale Temperature Accuracy: +/-0.8F from 32 to 120F (+/-0.44C from 0 to 50C) Temperature Range: -20 to 120F (-20 to 50C); 0 to 185F; 32 to 120F (0 to 50C); 40 to 110F (5 to 40C) Temperature Sensor: Remote Probe - Field Replaceable Unit Weight: 4.6 lbs Units/Pkg: 1

Warranty: 12-Month Limited

Dickson



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

Calibrations

N100: 1-Point NIST Traceable Calibration

- N300: 3-Point NIST Traceable Calibration
- N400: 3-Point Ultima NIST A2LA Accredited Calibration

Accessories



R250 - Replaceable Sensor Straight Temperature/Humidity Replaceable Sensor



A896 - Probe Extension Cable 10' Extension Probe for Straight Pre-Calibrated Sensor



R180 - Replacement AC Adapter AC Adapter for TSB/TWE/TWP Loggers and the KT8/KT6 series.



A868 - Sensor Dust Filter Sensor Dust Filter - prolong the life of your sensor.

Dickson



Phone: 1-800-757-3747 or 1-630-543-3747 | Fax: 1-630-543-0498 | Email: support@dicksondata.com | Website: DicksonData.com

Accessories



R066 - Universal Plug Kit for Data Loggers International Plug Kit for Data Loggers



A062 - AC Adapter Extension Cable 10' Power Extension for R157 AC Adapter